

## IMPORTANT NOTICE - VOLUNTARY PRODUCT RECALL

Dear Customer,

We have noticed a quality issue with the **LINEAR LED TURN** lights. In case of a strong vibration of the light unit, an internal insulation may potentially slip. It cannot be ruled out that, depending on the application situation, a residual risk of electric shock may remain in certain cases.



Three product types of this light series are affected, which are marked with the following "Ident Codes" numbers:

EAN/order number	product name/description	Ident Code
4058075227972	LINEAR LED TURN 557MM 3000K	AC354080055
4058075268388	LINEAR LED TURN 357MM 3000K	AC354090055
4058075576254	LINEAR LED TURN 557MM 830 SOEXT	AC354100055

The respective "Ident Code" can be found on the product label attached to the back of the lighting unit:



Only lights with the aforementioned three (3) Ident Codes are affected. LEDVANCE LINEAR LED TURN lights with other "Ident Codes" are not affected.

**To determine if you have purchased any of the affected products:**

- **First carefully disconnect the mains plug of the light from the socket.**
- **DO NOT touch the light unit while the mains plug is still plugged into the socket.**
- **Only remove the light unit once it has been fully disconnected from the socket.**
- **Check the ident code on the product label on the back of the light unit to see if it is affected by this recall notice.**
- **If so, please return the product to the original place of purchase or send it to the following address:**

LEDVANCE GmbH  
CQM  
Steinerne Furt 62  
86167 Augsburg

If you have any questions, please do not hesitate to contact us by phone at +49 (0)89 780 673-100 or by e-mail at [contact@ledvance.com](mailto:contact@ledvance.com).

We thank you in advance for your understanding and assistance, which helps to make an important contribution to the high quality and safety of our products.

Best regards,

LEDVANCE GmbH